





Origin: This corner was calculated on the split between the stone found at the southwest corner of Section 33 (ClCr_I25) and the rebar found at the southeast corner of Section 33 (ClCr_M25)

History and Search Procedure: The original GLO surveyor set a wooden post at this corner and took witnesses to a beech and a sugar maple. The Monroe County Surveyor, Andrew Dillman, used this corner to establish other corners in Section 33 in April of 1887 (Reference Survey ID 000025 - Monroe County Survey Book 2, pages 436-438), but he did not describe or witness a monument. No other references were found in the survey record.

There is an east/west fence along the south side of Ingram Road and an east/west fence along the north side that extends east from its beginning 22 feet east of the corner. We checked the road and the north bank for metal with our magnetic locator, but we did not excavate in the road, and we did minimal probing around the western end of the north fence and its westerly extension. No monument was found. There is a north/south mow line approximately in line with the west end of the east/west fence on the north side of the road, approximately 22' east of the corner.

Perpetuation: This monument was accepted by the Monroe County Surveyor Review Board on September 18, 2018. The monument was set and witnessed on July 16, 2018 (MCS Field Book 52, page 20).

Other Accessories:
Work done to preserve existing monument. A Monroe County Survey Marker sign was set 2.7' above grade on the north side of a 6" diameter natural split wood post with fence to the east and west on the south side of Ingram Road.

Vicinity Description: *Corner location relative to nearby features and how to reach the corner - note fences, roads, timber, streams, topo changes, etc.* The monument is in the approximate centerline of Ingram Road.

WITNESS MONUMENT TIES

All ties to new Bearing Trees (BTs) are a mag nail set in a hack mark at the root crown (less than 12" above ground) perpendicular to the center of the tree, unless otherwise noted. BT diameters are noted as dbh and are measured approximately 4.5' above ground. Bearings and distances were measured from the monument to the mag nail.

ID	*BEARING*	*DISTANCE*	*DESCRIPTION*
Witness A	N 11d W	22.7'	Mag nail and washer set 0.5' above grade in the east side of a 22" maple.
Witness B	N 43d E	33.8'	Mag nail and washer set 0.5' above grade in the west side of a 0.4' diameter round treated wood fence post with fence to the east.
Witness C	S 45d E	19.1'	Mag nail and washer set 0.7' above grade in the north side of a 21" maple.
Witness D	S 18d E	10.9'	Monroe County Survey Marker sign set 2.7' above grade in the north side of a 6" diameter natural split wood fence post on the south side of Ingram Road with fence to the east and west.
Witness E	N 34d W	76.1'	Southeast corner of house at 705 E Ingram Rd
Witness F	N 23d W	106.6'	Northeast corner of house at 705 E Ingram Rd

NOTES:

1. Field work was performed on July 16, 2018. Monroe County Surveyor's Field Book 52, page 20.
2. Project Name: ClCr_2018, Field work by: RSO & CAR, Drawn by: RSO, Reviewed by: RSO, TER & SRB.
3. The basis of bearings is Grid North System NAD83(2011)/Indiana West NAVD 88, Epoch 2010.0000, geoid12b_conus.db3, US Survey Feet, derived from GPS observations utilizing a Javad Triumph LS Rover and a Javad Triumph 2 Base. Static observations were post-processed using the JAVAD GNSS Data Online Processing Service (DPOS). Distances obtained with GPS have not been adjusted to ground. Coordinate data and witness ties were collected with a Javad Triumph LS Rover and a Sokkia Set 510 Total Station.
4. Vicinity sketch was compiled per 2017 aerial photography.
5. This document is not complete without the associated plat and report of survey for Section 33-T7N-R1W by Rachel Oser, of the Monroe County Surveyor's Office, dated 9/18/2018 and recorded as Instrument Number 2018012960 in the Monroe County Recorder's Office.

▲ **Monument Description:** A 5/8" rebar with a 2" aluminum Berntsen cap stamped "MONROE CO. SURVEYOR" was set 0.2' below grade in the approximate centerline of Ingram Road.
State Plane Grid Coordinates: Point No.:*5073* Northing: 1363958.2', Easting: 3111000.1'

SHEET 1 OF 2

MONUMENT RECORD
CORNER ID:
ClCr_K25

South Quarter Corner
Section 33- T07N-R01W
Clear Creek Township
Monroe County, Indiana

OFFICE OF THE MONROE COUNTY SURVEYOR
Trohn Enright-Randolph *Monroe County Surveyor*
Rachel Savich Oser *Professional Surveyor*
119 West 7th Street, Bloomington, IN 47404 (812) 349-2570

Photos were taken on 07/16/2018 with an iPhone 6s

SURVEYOR SEAL MONROE COUNTY INDIANA

MONROE COUNTY SURVEYOR REVIEW BOARD SEAL

RACHEL A. OSER REGISTERED No. 21100022 STATE OF INDIANA LAND SURVEYOR

Trohn Enright-Randolph
Monroe County Surveyor

Accepted by the Monroe
County Surveyor Review
Board on September 18, 2018

Rachel Savich Oser,
Indiana Professional Surveyor
No. 21100022



SHEET 2 OF 2	MONUMENT RECORD CORNER ID: **ClCr_K25**	**South Quarter Corner** Section 33- T07N-R01W Clear Creek Township Monroe County, Indiana	OFFICE OF THE MONROE COUNTY SURVEYOR **Trohn Enright-Randolph** *Monroe County Surveyor* **Rachel Savich Oser** *Professional Surveyor* 119 West 7th Street, Bloomington, IN 47404 (812) 349-2570

File path: N:\Monument_Records\T07N_R01W_ClearCreek\ClCr_K25\Draw\T07N_R01W_ClCr_K25_C3D.dwg Saved on: Sep 20, 2018 Plotted on: Sep 20, 2018